





- ◆ 按键: 开/关, 置零, 公/英制转换
- ◆ 自动关机
- ◆ 带数据输出(数据线货号:200-03 或200-04)

测厚表



单位: mm



货号	量程	分辨率	精度
461-010-11	0-10mm/0-0.4"	0.01mm/0.0005"	±0.02mm